

Appendix E – Footpaths & Drainage



Poor drainage to foot path in south west corner of the site. Water flows from higher ground to the left across the footpath. An existing drainage inlet is in the land to the right.



Poor drainage to the staff car park entrance road results in surface water from the road running down the foot path causing damage as shown. This has previously been repaired.



Drainage for the site and for Church Road is within this verge to the site which is no-longer being maintained. 3 gulleys are located in view of this image, all covered.



Example of frequent flooding on Church Road during construction due to poor maintenance of existing drainage.



Resulting damage to driveway from clay & silt deposits due to flooding.