

Appendix A – Aesthetics - Photo's & commentary

Staff Entrance - Views



Image taken October 2024




Source: Google Streetview May 2025 – view from Church Road



View of staff entrance from the footpath approaching from the south.

Siting of staff entrance in relation to heritage assets



Pre-development arrangement & setting of historic assets



Image from Google - 2017

General Aesthetics


Sevington & Church Road

Pre & post development aesthetic

Showing impact to setting & surroundings of historic assets & non-compliance with policy relating to aesthetics, design quality and separation of settlements.



Source: Google Streetview 2012 (nearest available pre-development date)



Source: Google Streetview May 2025



View of prefabricated buildings from the public footpath near to St Mary's Church.



Boundary treatment facing countryside – southern part of the site.



Example of how a buffer zone and existing hedging provide screening.



View towards St Marys Church from AE639 through the land to the east. St Marys can be seen to the left of the CCTV sign.



Areas where hedgerows appear to have been removed exposing the galvanised palisade fencing to the east of the site.



View towards St Mary's Church from the A2070 J10A link road to the north.



Detail view of St Marys Church from the A2070 J10A link.



Site main entrance



Existing ditch leading to Old Mill Stream near St Marys Church with adjacent site aesthetic.



View of the site adjacent to St Marys Church.



Views of buildings from the footpath across unplanted landscape in the position of the original route of AE639.



Example of alternative colour palisade fencing with appropriate planting at the DVLA site, Waterbrook, Sevington. The Vandgard anti-climb is also available in other colours including green. Whilst this example is in need of some maintenance, it demonstrates a more considered design of this type of boundary treatment.