


Responses Overview Active







1. The Sevington IBF was established via a Special Development Order (SDO) in December 2020. An application has been made to The Crown planning inspectorate to retain the site permanently.

This questionnaire is to gather feedback to help Sevington with Finberry Parish Council form its response to the application and is based on issues that have previously been raised.

Documents relating to the planning application can be viewed here: https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/application-information


The Parish Council will use this information to support a response to the consultation which ends on the 12th September 2025. It is important that you also make your views known via a direct response to the consultation on the 'Have Your Say' section of the link a bove.


The images in each section are the matters raised with the IBF consultation team during a meeting in November 2024.

2. Noise, both general noise and low frequency noise, has been a regular complaint of local residents. A new noise report has been submitt ed as part of the planning application that makes no reference to low frequency or tonal noise, whilst appearing to only consider noise fr om refrigerated trailers when electrically powered. The new noise report therefore appears to be less onerous on the operator than the o riginal report that formed the SDO, which required refrigerated trailers to be kept to the north of the site and may therefore lead to more noise as the site becomes fully operational.

Please select all options below that are relevant to your experience with the site and your consideration of the noise report.

The noise report can be viewed on this link: https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MOTD7FGDUL2UZBLOQP6YMVS6RAL





3. Please add any specific comments and concerns related to Noise below.

5 Responses Latest Responses

"The low frequency noise is unacceptable. We are told it's not measurable, but it d... "

...


5 respondents (100%) answered noise for this question.


noise bounces **noise** is unacceptable

- 4. The increase in HGV's on local roads has generated the following issues:
 - Navigating J10a during peak times can be problematic
 - Significant increase in litter, mostly in the form of discarded bottles filled with urine
 - HGV's making wrong turns causing issues on country lanes

There appears to be no mitigation proposed as part of the planning application.

Please select all options below that are relevant to your experience.





5. Please add any specific comments and concerns related to impact on local roads below.

11 Responses Latest Responses

- "HGV's are still constantly entering Church Road. They cause damage to residentia..."
- "Parking of HGVs and small vans around the front of the IBF have caused damage ... "

7 respondents (64%) answered Litter for this question.

bottles Litter traffic


6. Glare and poor control of light pollution from the site has been a continued issue.

The lighting report within the submitted documentation recognises issues relating to glare from the lighting and that the lighting is not compliant with local authority guidance.

The lighting report can be found on the link below which makes the recommendations shown.

 $\frac{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/01LFF32MKZCKABFB6YEFCILVRVK5EDHZIM}{\text{https://find-crown-development.planninginspectorate.gov.uk/applications/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d4633a1d00a9/documents/885d6bd3-c6b3-495f-a820-d460a9/documents/885d6bd3-c6b3-495f-a820-d460a9/documents/885d6bd3-c6b3-495f-a820-d460a9/documents/885d6bd3-$

Do you feel that this is suitable? Please select all that apply.





7. Please add any specific comments and concerns related to lighting below.

6 Responses Latest Responses

"Lights should've been situated on the perimeter facing into the site, NOT facing o..."

"Large areas of the site do not need to be floodlit. Assessments of the frequency o..."

...

4 respondents (67%) answered lights for this question.

curtains and blinds
areas of the site
times
Light pollution
glare from the lights

shift change lights

use of PIR

problem

IBF


light polution

Assessments of the frequency

8. Landscaping has generally been considered to be underwhelming and permitting greater views of the site than expected.

Some remedial planting is proposed, replacing existing planting which has failed, as highlighted by the areas of green in the masterplan below

Do you feel these proposals are suitable?




- The proposals fail to address poor quality topsoil to some areas (particularly to the south of the site).
 The proposals fall far short of what should be
- provided (please provide more detail on how you...

Other



12



9. Please add any specific comments and concerns related to landscaping below.

8 Responses Latest Responses

"Dead trees need replacing, and obvious gaps need filling. Another promise that \dots "

"Initially the planting etc was promising but it is now very disappointing that the u..."

...

5 respondents (63%) answered trees for this question.

wildflower we have is ragwort indiginous planting

Dead trees planting

grass areas landscaping

paths around the site

habitat for wildlife

mature trees Trees and shrubs

rees promised

better maintained

weeds

plenty of trees extensive planting bike path


10. Footpaths as re-located by the original development continue to experience drainage issues which washes away the surface in some are as and makes footpaths difficult to cross due to waterlogging in other areas.

Sevington with Finberry Parish Council with support of Mersham Parish Council also requested the re-instatement of the footpath through to the church and improvements to the footpath through to Mersham.

No changes to footpaths have been proposed.

Please select options below which reflect your views.

The footpaths do not have sufficient entry points for me to use them
The footpaths suffer continual drainage issues which need to be addressed
The footpath route is now too long, and the original route should be re-instated
The footpaths are poorly maintained
The footpaths are adequate as they are
Other



11. Please add any specific comments and concerns related to footpaths below.

5 Responses Latest Responses

"The path is poorly located, close to residents, and poorly maintained."

"Poorly maintained footpaths that are either sodden with water or being eroded b... "

• • •

4 respondents (80%) answered footpaths for this question.


footpaths Poorly maintained

Dog waste

12. Site aesthetics are generally poorer than expected, with a poor frontage to A2070, metal fencing to countryside walks, poor site entrance and views of buildings that are temporary in nature and without any architectural design.

The planning application does not appear to make any proposals to improve aesthetics

Please select all options below that reflect your views.



13. Please add any specific comments and concerns related to aesthetics below.

7 Responses Latest Responses


- "The site appearance is absolutely appalling. It's like living next to a prison, with g... "
- "The front aesthetics are very poor. The litter strewn in the grass, authorised parki..."


...

razor wire signage and bollards lorries HGV drivers fencing and rolls fencing staff entrance palisade fencing open appearance baths on the pavements site perimeter lack of signage

14. Archaeology was undertaken during the original construction period with locally and regionally significant findings.


Please select all options that reflect your views:






15. Negotiated mitigation not delivered


The previous proposed development had proposed mitigation measures, some of which were particularly relevant to Sevington resident s. Each of these are listed below. Please select all views that you agree with.





16. CCTV Cameras

Reports that CCTV Cameras are intrusive, close to homes and monitoring the public footpaths. Please select all views that you agree with





17. Other Items

Please list below any other matters you wish to raise.

5 Responses Latest Responses

"The whole IBF issue has caused untold misery for residents and affected my ment..."

"Pollution - i am concerned about the disregard of the rise in Pollution around the..."

2 respondents (40%) answered site for this question.

property unsellable home and garden curtains and blinds peaceful and tranquil site has an impact misery for residents vehicle traffic **misery**


health of the residents property site damage

untold misery testing around the site site and the residents IBF issue appalling

No compensation rise in Pollution admission of damage

18. To ensure that responses are genuine, we need a few details from you. Please select your location:






19. Please enter your full postcode below

22 Responses Latest Responses
"TN24 0LD"
"TN24 0LD"
"Tn240le"

ひ Update 7 respondents (33%) answered TN24 for this question. **TN25 7GE TN14 0FN** TN256NL TN24 0TW TN24 0LL Tn24 Olf **TN23 5YH TN257GU** TN23 Tn25 **TN24 0LD** Tn270lb Tn25 7nb **TN24 0TP TN24 0LJ TN23 3PD** tn23 3pf adfsdf Tn234qp

20. Please enter your name (or initials) below.



21. If you would like to be kept up-to-date, please enter your email address below

