


## Appendix G – Traffic & Litter – Supporting information & photo's.



Google maps traffic data – average travel time at 17:30 on a Wednesday. Showing significant congestion on unsignalled A20 entry points to junction 10A.



Examples of disruption caused by HGV's getting into difficulties on Church Road.



Image of HGV requiring recovery from the front garden of Sunnybank



Most recent example from 18<sup>th</sup> November 2025.



Example of common type of litter – bottle with human waste. A2070 J10A Link near to IBF entrance.



Litter & dog waste bin. Only one found on the footpaths around the site.