


Appendix D – Lighting – Supporting images

The following images show glare and reflectance from building attached lighting, reported as turned off within the lighting impact assessment (Image November 2025).



The following are recent images following fitting of baffles, local dimming and switching off of lighting. Light continues to spread to biodiversity retained areas.





View of the site from AE639 from Mersham



View of the site from bridleway adjacent to St Mary's Church



Previous images as submitted showing difference in luminaire design and glare



Comparison with new A2070 street lighting which has significantly better light pollution performance